

.

support@ipitomy.com | 941.306.2200 (Opt 2 for Support)

You are viewing the IPitomy IP PBX Manual, [Table of Contents](#).

Power spike - brown out / unpower system

It has been noted that after a brown out condition with the power source, it may prove necessary to perform a power reset on the PBX as the power supply may go into a protection status and this is the only way to clear this condition.